


# XL Base Assembly Instructions

### Parts Included:


- A Welded foot (with glides)
- B Column
- C Mounting plate (with set screw "D")
- D Set Screw
- E Rod
- F Phillips pan head screws
  - Optional casters

## **Tools Needed:**

Phillips screwdriver or impact drill 3/8" hex bit 18mm socket Safety glasses



If you are missing parts or have any questions about the product, please call Customer Service at 888,705-0777.



#### Instructions

#### **Base Assembly:**

- 1. Place column (B) on top of the welded foot (A)
- 2. Place mounting plate (C) on top of the column (B) NOTE: set screw (D) must be inserted in the slot on the top of the column.
- Insert rod (E) through the mounting plate (C) and column (B) and screw into the welded foot. Tighten the rod with 19mm socket.

NOTE: If using optional casters, install them on the welded foot (A).



START BOLTS BY HAND TO PREVENT CROSS THREADING

11.2012

678-879-0777: phone www.specialT.net

678-456-6046: fax